🕅 NICHIAS

Case study: Air purifying unit particle generation TOMBO[™] No. 8803-ZAE2 (Honeycle[™] ZAE2)





Industry

Contamination control in medical sector

Customer

Air purifier systems manufacturer

Background

Customer was experiencing issues with one of their large air volume purification units for use in hospitals. These units were using plasma to eliminate bacteria, viruses, and other contaminants from air. However, at times, aside from purified air, the unit also began releasing fine, dark particles. First noticed and complained about by one of their end users, customer halted production until they were able to resolve the issue. This not only affected their sales but also the safety of all the other machines and future production. The customer needed to identify the source of the particle generation, find a solution that would cause minimal disruptions and finish the works in as quick time as possible in order to minimize losses.

Challenges faced

The main challenge was to find the source of the particle generation. There were no particles entering the system on the process inlet air side which meant that the particle generation occurred inside the machine. After further review and analysis, the source was identified as the activated carbon filter used in the unit. This discovery presented more challenges. Customer preferred a catalyst with odour removing abilities. So, they had to find a new filter supplier with material that eliminated particle generation and maintained the performance of the unit.

Solution and benefits

The technical team in NICHIAS analysed the unit's filter and identified that the catalyst was not properly impregnated into the substrate which meant that the catalyst was detaching from the substrate and releasing into the air. Customer wanted to keep the same catalyst as part of the functional material for ozone removal. Thankfully, NICHIAS had already invested in the development of a better catalyst-binder technique which resulted in the manufacture of TOMBO No. 8803-ZAE2. This filter is made from MnO₂ and catalyst on aluminium honeycomb core. After series of tests in customer's application, it was confirmed that no defect particle generation occurred. Adopting TOMBO No. 8803-ZAE2 also offered a lower pressure drop and high removal efficiency which improved the unit's overall performance. As a result, customer was able to install NICHIAS' filter into all the unit and relaunch the systems on the market.

For more information, please visit: https://nichias.co.jp/en



*TOMBO is a registered trademark of NICHIAS Corporation. *Products with TM are trademarks of NICHIAS Corporation. Honeycle™ filter substrates

NICHIAS Corporation

Head Office

6-1, Hatchobori 1-chome, Chuo-ku, Tokyo 104-8555, Japan International Marketing and Sales Group Phone: 81-3-4413-1132 Fax: 81-3-3552-6108 Web Site: https://www.nichias.co.ip/

Overseas Sales Companies

Indonesia

PT. NICHIAS SUNIJAYA Seguis Tower Level 19 Suite 1&2. JI. Jend Sudirman Kav. 71, Jakarta 12190, Indonesia Phone: +62-21- 2277-6101 Fax: +62-21- 2793-8033 Malaysia

NICHIAS SOUTHEAST ASIA SDN. BHD.

Suite A1102, 11th Floor, West Wing, Wisma Consplant 2, No. 7, Jalan SS 16/1, 47500 Subang Jaya, Selangor Darul Ehsan, Malaysia. Phone: +60-3-5636-4067 Fax: +60-3-5636-4078

Singapore

NICHIAS SINGAPORE PTE. LTD. 25 International Business Park, #01-15/17 German Centre,

Singapore 609916

Phone: +65-6571-0830/0838 Fax: +65-6265-7681 Vietnam

NICHIAS VIETNAM CO. LTD

Room 709, Elite Business Center, 7th Floor Diamond Flower Building, 48 Le Van Luong Street, Nhan Chinh Ward, Thanh Xuan District, Hanoi, Vietnam

Phone: + 84-24-6664-3136 Fax: + 84-24-6666-8168

Thailand

NICHIAS (THAILAND) CO., LTD. 85 Moo 1, Wellgrow Industrial Estate T. Homsin, A. Bangpakong

Chachoengsao 24180, Thailand Phone: +66-38-570-600 Fax: +66-38-570-601

THAI NICHIAS INTERNATIONAL CO., LTD.

Unit 1107, 11th Floor, AIA Capital Center

89 Ratchadaphisek Road, Dindaeng, Dindaeng, Bangkok 10400 Thailand Phone: +66-2-001-2060 Fax: +66-2-001-2062

China

NICHIAS (SHANGHAI) TRADING CO., LTD.

霓佳斯 (上海) 贸易有限公司

Room 1701, THE PLACE, Tower A, No. 100 Zun Yi Road, Changning District, Shanghai, P.R.China, Postcode 200051 中国上海市长宁区遵义路100号虹桥南丰城A栋1701室 邮编200051 Phone: +86-21-6236-1783 Fax: +86-21-6236-1781

NICHIAS (SHANGHAI) TRADING CO., LTD. Guangzhou Branch 霓佳斯(上海)贸易有限公司 广州分公司

17F-G, Gold Sun Building, No.109 Tiyu West Road, Guangzhou, Guang Dong Province, 510620, P.R.China 中国广东省广州市天河区体育西路109号高盛大厦17楼G室 邮编 510620 Phone: +86-20-3879-1640 Fax: +86-20-3879-1647

NICHIAS (SHANGHAI) AUTOPARTS TRADING CO., LTD.

霓佳斯(上海)汽车零部件贸易有限公司

Room 1702, THE PLACE, Tower A, No. 100 Zun Yi Road, Changning District, Shanghai, P.R.China Postcode 200051 中国上海市长宁区遵义路100号虹桥南丰城A栋1702室 邮编200051 Phone: +86-21-6236-2668 Fax: +86-21-6236-2667

A Cautions

- The products included in this catalog are intended for common use, including those presented in the catalog. If you intend to use any of the products in a way that requires extremely high quality and reliability such that any possible defect may directly affect the safety of human lives, please make sure to consult with our company in advance and take necessary measures at hydrogeneobility. our responsibility.
- your responsibility. Because the stated material values may vary according to actual usage environments or circumstances, please consider such figures as indications for reference. The content of the catalog explains the features of the products when they are used alone. When actually using the products, please start using them after testing them under the actual when actually using the products, please start using them after testing them under the actual
- When actually using the products, please start using them after testing them under the actual usage environment.
 The content of the explanation of the products may be modified without any advance notice, and the production of the product may also be discontinued without advance notice. Please obtain the latest version of the catalog, and confirm the content thereof. The date of issuance of this catalog is printed on this page.
 The standards, accreditation and provisions of laws included in the catalog may not conform with the latest version thereof.
 We strictly prohibit any acts of infringement upon our rights that are protected by the Copyright Act with regard to information included in the catalog, through the production of copies or imitations, misappropriation or unauthorized reprinting.

Overseas Construction Companies

Malaysia NICHIAS SOUTHEAST ASIA SDN. BHD.

Suite A1102, 11th Floor, West Wing, Wisma Consplant 2, No. 7, Jalan SS 16/1, 47500 Subang Jaya, Selangor Darul Ehsan, Malaysia. Phone: +60-3-5636-4067 Fax: +60-3-5636-4078 Thailand

THAI-NICHIAS ENGINEERING CO., LTD.

45 Huaypong-Nongbon Road, Huaypong, Muang Rayong, Rayong Province 21150, Thailand Phone: +66-38-682-242 Fax: +66-38-691-156

Overseas Factories

- Indonesia PT. NICHIAS ROCKWOOL INDONESIA PT. NICHIAS METALWORKS INDONESIA Malaysia NICHIAS FGS SDN. BHD. NT RUBBER-SEALS SDN. BHD. Vietnam NICHIAS HAIPHONG CO., LTD. China SUZHOU NICHIAS INDUSTRIAL PRODUCTS CO., LTD. (苏州霓佳斯工业制品有限公司) SUZHOU NICHIAS SEAL MATERIAL CO., LTD. (苏州霓佳斯密封材料有限公司) SHANGHAI XINGSHENG GASKET CO., LTD. (上海兴盛密封垫有限公司) SUZHOU SHUANGYOU AUTOPARTS CO., LTD. (苏州双友汽车零部件有限公司) India NICHIAS INDUSTRIAL PRODUCTS PRIVATE LTD. Czech NICHIAS AUTOPARTS FUROPE a s Mexico
- NAX MFG, S.A.DE C.V.

- Please be informed that, in the case where any problem involving a third party's industrial
 property right arises due to the use of any product included in the catalog, our company shall
 not be responsible for any problems other than the problems arising strictly due to reasons
 related to only such products.
- Please be aware that our company will not bear any responsibility for the following damage related to our products: -Damage arising due to natural disasters or accidents occurring for reasons that are not

 - Damage arising due to natural disasters or accidents occurring for reasons that are not attributable to our company;
 Damage arising due to remodeling, repairing or other acts by a third party;
 Damage arising due to the willful intent or negligence of the customer or the user, or due to the improper use or use under abnormal conditions of the products;
 Damage arising due to the failure to carry out regular checkups and appropriate repairs, maintenance and part replacements, considering various conditions, such as the usage conditions, usage environment and usage period, etc., of the product;
 Indirect damage (including any operational damage, lost profits, opportunity losses, etc.) arising due to the use of or inability to use our company's product;
 Damage arising due to a situation which was unforeseeable under the technical standards at the time of the shipment of our company's product; or
 Damage ansing due to reasons that are not attributable to our company.



Printed in Japan E38-2103-02-PA-SH-RE-1805